Room marked 2, no longer used

ACCESS TO FARMYARD

existing wall to be stabilised and made good

new gate for field access

PARKING
(60 spaces including 3 disabled)

existing stables building demolished

DELIVERIES

KITCHEN / BAR

EXISTING AGRICULTURAL STORE

HALL 2

FFL 198.30

Sparrow nest cups installed in barn - access through high level window
Refer to Ecologist's report

HALL 1

TERRACE
FFL 198.41

Form bat roost in roof space as per Ecologist's report (8.6 x 6.3 x 1.8m)

EXISTING AGRICULTURAL STORE

TERRACE
FFL 198.90

EXISTING AGRICULTURAL STORE

BRIDAL SUITE

New stone wall

conversion of existing garage

TERRACE
FFL 199.70

Gate

EXISTING FARMHOUSE

Robin and wren nest box in tree.
Refer to Ecologist's report

Gate

OUTDOOR CEREMONY AREA

New rotunda for outdoor ceremonies

New haha

Direction of slope

Barn owl nest box in tree.
Refer to Ecologist's report

0m 5m 10m

revisions		initial	date
D	Ecological measures added	DC	12.09.19
C	Bat mitigation amended	DC	16.07.19
B	Bat mitigation added	DC	16.07.19
A	Parking amended	DC	19.06.19

Contractors, Sub Contractors and Suppliers are to check all relevant dimensions and levels of site and buildings before commencing any shop drawings or building work.

This drawing is copyright and may not be reproduced in any part of form without the written consent of Fowler Architecture and Planning

project
LIDDINGTON WARREN FARM
Liddington Warren

drawing
site plan

scale	drawn by	date
1:200@A1	DC	June 2019

drawing no	rev
170403-13	E

FOWLER ARCHITECTURE & PLANNING
19 High Street
Pewsey
Wiltshire
SN9 5AF
tel (01672) 569444
enquiries@faap.co.uk